

Title: Single Phase Transformers

Date: 23/03/2020

Name of Faculty: Ms. Richa Dubey


Lecture No: 06

Source of information: B. L. Theraja, "Electrical Technology – Part I and


II", S. Chand and Co. 2012

Page no.

Cut view of transformer




Transformer with conservator and breather



Working of a transformer

- 1. When current in the primary coil changes being alternating in nature, a changing magnetic field is produced
- 2. This changing magnetic field gets associated with the secondary through the soft iron core
- 3. Hence magnetic flux linked with the secondary coil changes.
- 4. Which induces e.m.f. in the secondary.



Single Phase Transformer




FIGURE 4.8 A transformer circuit.

- A single phase transformer
 - Two or more winding, coupled by a common magnetic core

Ideal Transformers

Zero leakage flux:

-Fluxes produced by the primary and secondary currents are confined within the core

The windings have no resistance:

- Induced voltages equal applied voltages


The core has infinite permeability

- Reluctance of the core is zero
- Negligible current is required to establish magnetic flux

Loss-less magnetic core

- No hysteresis or eddy currents

Ideal transformer



 V_1 – supply voltage;

V₂- output voltgae;

I_m- magnetising current;

E₁-self induced emf;

I₁- noload input current;

I₂- output current

E₂- mutually induced emf

EMF equation of the Transformer

```
Let, N_1 = Number of turns in primary winding N_2 = Number of turns in secondary winding \Phi_m = Maximum flux in the core (in Wb) = (B_m x A) f = frequency of the AC supply (in Hz)
```

Therefore, average emf per turn = $4f \Phi_m$ (Volts).

```
As, shown in the fig., the flux rises sinusoidally to its maximum value \Phi_m from 0. It reaches to the maximum value in one quarter of the cycle i.e in T/4 sec (where, T is time period of the sin wave of the supply = 1/f). Therefore, average rate of change of flux = \Phi_m /_{(T/4)} = \Phi_m /_{(1/4f)} Therefore, average rate of change of flux = 4f \Phi_m ...... (Wb/s). Now, Induced emf per turn = rate of change of flux per turn
```

Now, we know, Form factor = RMS value / average value Therefore, RMS value of emf per turn = Form factor X average emf per turn.

As, the flux Φ varies sinusoidally, form factor of a sine wave is 1.11

Therefore, RMS value of emf per turn = $1.11 \times 4f \Phi_m = 4.44f \Phi_m$.

RMS value of induced emf in whole primary winding (E_1) = RMS value of emf per turn X Number of turns in primary winding

$$E_1 = 4.44f N_1 \Phi_m$$
eq 1

Similarly, RMS induced emf in secondary winding (E₂) can be given as

$$E_2 = 4.44 f N_2 \Phi_m$$
. eq 2

from the above equations 1 and 2,

This is called the **emf equation of transformer**, which shows, emf / number of turns is same for both primary and secondary winding.

For an <u>ideal transformer</u> on no load, $E_1 = V_1$ and $E_2 = V_2$. where, V_1 = supply voltage of primary winding V_2 = terminal voltage of secondary winding

All day efficiency

ordinary commercial efficiency = $\frac{\text{out put in watts}}{\text{input in watts}}$

$$\eta_{all \text{ day}} = \frac{\text{output in kWh}}{\text{Input in kWh}} (for 24 \text{ hours})$$

•All day efficiency is always less than the commercial efficiency

Assignment:

- 1) Define transformers and explain working and construction of single phase transformers?
- 2) What is Ideal Transformers?

For any Query pl Contact: Ms Richa Dubey (9998037615) richa.dubey@srict.in